

PAGE 02/03

KAM CONSULTANTS

7187293774

03:11:03 1007/07/11

CITY_21MC100_002988328



33-40 30th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

FOR ASBESTOS AIR MONITORING

SAMPLING DATE: 11-6-01
ADDRESS: 345 Chambers St., NY, NY 10282

TD/1106D

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ³)	Structure Concentration (struc/cc)
							0.5-5.0 (µ)	>5.0 (µ)		
1	North Entrance of school East	8:02	16:00	3	3	1434	0	0	<16.67	<16.67
2	11 - 11 - West	8:04	16:02	3	3	1434	0	0	<16.67	<16.67

RECEIVED
KAM CONSULTANTS
2001 NOV - 6 PM 5:25

TECHNICIAN: R. DYMKOWSKA

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results to DDC.	RECEIVED AT LAB BY:
		SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST: *[Signature]*

DATE RECEIVED: 11/6/01

DATE OF ANALYSIS 11/7/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 703 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 041-5356