



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-12-01
ADDRESS: 345 Chambers St., NY, NY 10282

10/10/12F

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (rpm)	FLOW AFTER (rpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (shuc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
	PIER-25									
1	North Entrance of school - East	8:01	15:56	3	3	1425	0	0	<16.67	<0.0045
2	North Entrance of school - West	8:04	15:59	3	3	1425	0	0	<16.67	<0.0045

RECEIVED
KAM CONSULTANTS
OCT 12 PM 5:05

TECHNICIAN: Renata Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE Analyze ASHP and FAX Results!	RECEIVED AT LAB BY: <i>[Signature]</i>
	DOC Macbat (718) 291-1443	
	DOC OPERATIONS (212) 941-5356	SAMPLE CONDITION UPON RECEIPT:
	DOC BOB ADAMS (609) 584-1134	DATE/TIME: 10/12/01

ANALYST: DAVE CAPEN

DATE RECEIVED: 10/12/01

DATE OF ANALYSIS 10/12/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (ASHERA)

Sample Volume may be below recommended limit of the method.

FAX RESULTS TO (212) 941-5356