NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718)729-1997
Fax: (718)729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10/13/01
ADDRESS: 345 Chambers St., NY,NY 10282

T 01/013 B

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	00.01	7.53	3	3	1416	0	0	<16.67	<0.0045
2	- WEST SIDE	00.03	7.53	3	3	1416	0	0	<16.67	<0.0046

TECHNICIAN: A. MARTIROSSIAN
ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE ANALYZE ASAP AND FAX RESULTS DDC HAZMAT (718) 391-1499 DDC OPERATIONS (212) 941-5358 BOB ADAMS (609) 588-1134	RECEIVED AT LAB BY: ML SAMPLE CONDITION UPON RECEIPT: DATE/TIME: 10/13

ANALYST: A Martirossian
DATE RECEVED: 10/13/01
DATE OF ANALYSIS 10/13/01 1 Day

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

RECEIVED
KAM CONSULTANTS
2001 OCT 13 AM P. 51

10/13/2001 12:25 7187293774 KAM CONSULTANTS PAGE 01/02
CITY_21MC100_00298839
NYC-WTC_000205411