

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876



CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-18-01
ADDRESS: 345 Chambers St., NY, NY 10282

T011019A

[illegible]

TECHNICIAN: R. Dymkowski

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results to DDC	RECEIVED AT LAB BY:	
		SAMPLE CONDITION UPON RECEIPT:	
		DATE/TIME:	

ANALYST:

DATE RECEIVED:

DATE OF ANALYSIS

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356