NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10/28/01
ADDRESS: 345 Chambers St., NY, NY 10282

T011029C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION DIER #25	TIME IN	TIME OUT New WINTER TIME	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EPA 5100	00.01	8:00	3	3	1617	0	0	<20.0	<0.0047
2	↓ - ROSE F100	00.02	8:02	3	3	1620	↓	↓	↓	↓
			9h							

TECHNICIAN: A. MONDRAGON/R. Dymkowska ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE ANALYSE ASAP AND FAX RESULTS DDC HAZMAT (718) 391-1499 DDC OPERATIONS (212) 941-5356 BOB ADAMS (609) 584-1134	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: ALEKS BARLOWSKI DATE RECEVED: 10/29/01 DATE OF ANALYSIS 10/29/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

RECEIVED
KAM CONSULTANTS
2001 OCT 29 PM 5:27

10/29/2001 11:48 7187293774 KAM CONSULTANTS PAGE 03/03

CITY_21MC100_002988482

NYC-WTC_000205414