NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10/31/01
ADDRESS: 345 Chambers St, NY, NY 10282

RECEIVED
KAM CONSULTANTS
2001 OCT 31 PM 5:29

To11031G

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION DAER #25	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	00-01	8:00	3	3	1437	0	0	<16.67	<0.0045
2	↓ - WEST SIDE	00-02	8:02	3	3	1440	↓	↓	↓	↓

TECHNICIAN: A. MARTIROSSIAN / R. DYNKOWSKA ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE, ANALYSE ASAP AND FAX RESULTS DDC HAZMAT (718) 391-1499 DDC OPERATIONS (212) 961-5356 BOB ADAMS (609) 584-1134	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: A. Martirossian DATE RECEVED: 10/31/01 DATE OF ANALYSIS 10/31/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

10/31/2001 20:52 7187293774 KAM CONSULTANTS PAGE 01/02
CITY_21MC100_002988491
NYC-WTC_000205415