NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1676

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10/11/01
ADDRESS: 345 Chambers St., NY, NY 10282

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	Piez #25 North East at Stuyvesant H. S.	1600	2400	3	3	1440	0	0	<16.67	<0.0045
2	Piez #25 North West at Stuyvesant H. S.	1601	2401	3	3	1440	1	0	16.67	0.0045

RECEIVED
KAM CONSULTANTS
2001 OCT 12 AM 5:17

TECHNICIAN: DIMITRIOS M. SALIS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results TO DDC DDC Hotline (718) 391 1499 DDC Operation Fax 941 5356 DDC Bob Adams (609) 584 1134	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: [signature] DATE RECEIVED: 10/11/01 DATE OF ANALYSIS 10/11/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

PAGE 01/01
KAM CONSULTANTS
7187293774
10/12/2001 07:47
CITY_21MC100_00298502

NYC-WTC_000205417