

35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876



CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC

SAMPLING DATE: 10-26-01

PROJECT: Stuyvesant H.S.

ADDRESS: 345 Chambers St., NY, NY 10282

[illegible]

TECHNICIAN: R. Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results to DDC.	RECEIVED AT LAB BY: <i>VS</i> SAMPLE CONDITION UPON RECEIPT: DATE/TIME:
------------------------	---------------------	---

ANALYST:

ALIK

Blumen

DATE RECEIVED:

10/26/01

DATE OF ANALYSIS

10/27/0

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method.

FAX RESULTS TO (212) 841-5350

10/27/2001

11:25

7187293774

KAM CONSULTANTS

PAGE 03/03