

**C
L
E**

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue, Bronx, New York 10465 ☎ (718) 792-2832

Duane Street Associates c/o
Hudson River Management LLC.,
40 Harrison Street
New York, NY.

10013

Attn.: Ms. Deborah Dolan.

File #: 01231-B3.

Project: Building # 3 – 40 Harrison Street, New York, NY.

Location: 14th Floor – Various locations.

Samples collected on: October 29, 2001.

Type of test: TEM – Air Quality Tests.

Industrial Hygienists: Victor Escalona.
Maria Escalona.

AH 90-16572. Rotameter #: 1.
AH 98-01434.


**REPORT
ASBESTOS FIBER ANALYSIS BY
TRANSMISSION ELECTRON MICROSCOPY (TEM)
Performed by EPA 40 CFR Part 763 Final Rule, EPA Level II.**

Sample #:	Location:	Flow Rate (lts/min)		Time of test.		Duration (minutes)	Volume (liters)	Results Fibers/cc
		ON	OFF	ON	OFF			
338	South side corridor.	10.0	10.0	8:40am – 11:05am		145	1450	***
339	Middle of corridor by elevator.	10.0	10.0	8:41am – 11:06am		145	1450	***
340	East side corridor.	10.0	10.0	8:42am – 11:07am		145	1450	***
341	Inside apartment # 14H; by windows area.	10.0	10.0	8:45am – 11:10am		145	1450	***
342	Inside apartment # 14A; by windows area.	10.0	10.0	8:47am – 11:12am		145	1450	***
	Apt. # 14H: Rotsky Family.							
	Apt. # 14A: Scottboyce Family.							

TEM air samples were analyzed by EMSL Analytical, Inc.; accredited for NVLAP TEM # 101048-10; NYS DOH ELAP Certificate #: 11469. Lab Report reference # LI01-16410.

This report must not be used by the client to claim product endorsement by NVLAP or NYS DOH ELAP or any agency of the US Government. This report relates only to the items listed. This certificate or report shall not be reproduced except in full, without the written approval of the laboratory.

*** See laboratory table for results of analysis.


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_003008213