NYC 9/11 Public Portal Document

C L E **COMMERCIAL LAB ENTERPRISE**

270 Swinton **Avenue, Bronx, New York 10465 ☎ (718) 792-2832**

Duane Street Associates c/o
Hudson River Management LLC.,
40 Harrison Street
New York, NY.
10013
Attn.: Ms. Deborah Dolan.

File #: 01231-B3.

Project: Building # 3 – 40 Harrison Street, **New York, NY.**
Location: 11th Floor – Various locations.
Samples collected on: October 29, 2001.
Type of test: TEM – Air Quality Tests.
Industrial Hygienists: Victor Escalona. **AH** 90-16572. **Rotameter #:** 1.
Maria Escalona. **AH** 98-01434.

REPORT
ASBESTOS FIBER ANALYSIS BY
TRANSMISSION ELECTRON MICROSCOPY (TEM)
Performed by EPA 40 CFR Part 763 Final Rule, EPA Level II.

Sample #:	Location:	Flow Rate (lts/min) ON	OFF	Time of test. ON	OFF	Duration (minutes)	Volume (liters)	Results Fibers/cc
353	South side corridor.	10.0	10.0	10:10am – 12:30pm		140	1400	***
354	Middle of corridor by elevator.	10.0	10.0	10:11am – 12:31pm		140	1400	***
355	East side corridor.	10.0	10.0	10:12am – 12:32pm		140	1400	***
356	Inside apartment # 11G; by windows area.	10.0	10.0	10:14am – 1:00pm		166	1660	***
357	Inside apartment # 11L; by windows area.	10.0	10.0	10:16am – 12:36pm		140	1400	***
	Apt. # 11G: Anzalone Family.							
	Apt. # 11L: Rogers Family.							

TEM air samples were analyzed by EMSL Analytical, Inc.; accredited for NVLAP TEM # 101048-10; NYS DOH ELAP Certificate #: 11469. Lab Report reference # LI01-16410.
This report must not be used by the client to claim product endorsement by NVLAP or NYS DOH ELAP or any agency of the US Government. This report relates only to the items listed. This certificate or report shall not be reproduced except in full, without the written approval of the laboratory.
*** See laboratory table for results of analysis.

Project Manager

ENVIRONMENTAL CONSULTING SERVICES

NYC-WTC_000205593