

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0056 Email:

EMSL

Attn: L. Sharon
CTSI-Consulting & Testing Services, Inc.
622 Georges Rd.
North Brunswick, NJ 08902
Fax: (732) 729-1803 Phone: 732-729-1800
Project: 200 WATER STREET

Customer ID: CTS150
Customer PO:
Received: 09/20/01 8:40 AM
EMSL Order: 030104576
EMSL Project ID:
Analysis Date: 9/20/2001

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
01 030104576-0001	ROOM 529			None Detected	
02 030104576-0002	ROOM 623			None Detected	
03 030104576-0003	ROOM 1018			None Detected	
04 030104576-0004	ROOM 1609			None Detected	
05 030104576-0005	ROOM 1202			None Detected	
06 030104576-0006	ROOM 1007			None Detected	
07 030104576-0007	ROOM 909			None Detected	
08 030104576-0008	ROOM 818			None Detected	
09 030104576-0009	ROOM 1503			None Detected	
10 030104576-0010	ROOM 1506			None Detected	



Analyst

Laboratory Manager
or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

ACCREDITATIONS: NVLAP #101048-9 and NY STATE ELAP #11506

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: L. Sharon
CTSI-Consulting & Testing Services, Inc.
622 Georges Rd.
North Brunswick, NJ 08902
Fax: (732) 729-1803 Phone: 732-729-1800
Project: 200 WATER STREET

Customer ID: CTS150
Customer PO:
Received: 09/20/01 8:40 AM
EMSL Order: 030104576
EMSL Project ID:
Analysis Date: 9/20/2001

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
11 030104576-0011	ROOM 816			None Detected	
12 030104576-0012	ROOM 1105			None Detected	
13 030104576-0013	ROOM 2418			None Detected	
14 030104576-0014	ROOM 1102			None Detected	



Laboratory Manager
or other approved signatory

Analyst

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced except in full without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

ACREDITATIONS: NVLAP #101046-5 and NY STATE ELAP #11508