



**Recovery Physical Therapy
Air Monitoring for Asbestos, Respirable Dust, and Priority Pollutant Metals
Basement Therapy Room, 79 Maiden Lane, New York, NY**

Advanced Environmental Corp.

Appendix A

Summary of TEM Air Sample Results

SciLab Job #: 202022107

Client Name: Advanced Environmental Corp.

Table I
Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)
 1213.001; Recovery Physical Therapy; 79 Maiden Lane, New York, NY

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)			Structure Density (struc/sq. mm.)		Structure Concentration (struc/cc air)		Type of Asbestos
						0.5-5.0	>5.0	Total	>5.0	Total	>5.0	Total	
01	021202-TEM01 Therapy Room		1251	.07	0.0044	0.0	0.0	0.0	<14.3	<14.3	<0.0044	<0.0044	NSD

* concentration represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By:



; Analyzed By:


 Paul Mucha

Date: 2/14/02

NVLAP#: 200546-0

TOTAL P. 02

2/25/2002 08:03 2125450757
 FEB-14-2002 12:53 SCIENTIFIC LABS

ADVANCED ENVIRONMENT

212 679 9392 P. 02/02
 PAGE 05