



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: 9 Murray		2. Project Name: 9 Murray St NY NY		3. Project #: 09121101		4. Project Monitor: David Chang		4c. Rotameter Number: 30-130	
5. Date: 9/12/01		6. Abatement Location: W Lobby		7. ☒ PCM (0.3 micron MCE) Cassella Filter Manufacture Lot # 01044915		8. ☐ TEM (0.45 micron MCE) Cassella Filter Manufacture Lot # 01044915		9. Type: a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA	
								f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
WL-01				Field Blank								0/100	
EL-01				Field Blank								0/100	
WL-02		V		West Lobby West Side	1440	1640	120	15	15	15	1800	3/100	40003
WL-03		V		West Lobby East Side	1442	1642	110	15	15	15	1802	5/100	40003
EL-02				East Lobby West Side	1453	1653	120	15	15	15	1800	4/100	40003
EL-03				East Lobby East Side	1454	1654	120	15	15	15	1800	7/100	40003

CHAIN OF CUSTODY

18. Relinquished By: I. [Signature]	19. Received By: David Chang	20. Date: 09/12/01	21. Time: 1900
II			
III			

26. ATC Project Manager: David Chang	27. Result To: David Chang Beeper/Phone #'s
--	---

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: a. Analyzed By: [Signature] b. QC By: c. Lab Batch #: 97155	23. Date: 09/12/01	24. Time: 1925	25. Microscope Make/Serial #: Nikon Labophot 238913 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
28. Comments:			Analyst Methodology ☒ PCM - NIOSH 7400A TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

004

ATC

10/08/2001 10:02 FAX 212 353 8306

CITY_21MC100_011087543