



CLIENT: New York Law School

LOCATIONS: 47 Worth Street, 53 Worth Street
57 Worth Street, 240 Church Street
New York, NY

Warren & Panzer Engineers, P.C.

228 East 45th Street

New York, New York 10017

Tel. (212) 922-0077

Fax (212) 922-0630

Ambient Air Sampling Results

SAMPLE IDENTIFICATION NUMBER	BUILDING ADDRESS	LOCATION	LABORATORY ANALYSIS RESULTS
			Transmission Electron Microscopy (TEM)
01	47 Worth Street	5 th Floor	No Structure Detected
02	47 Worth Street	4 th Floor	No Structure Detected
03	47 Worth Street	3 rd Floor	No Structure Detected
04	47 Worth Street	2 nd Floor	No Structure Detected
05	47 Worth Street	1 st Floor	No Structure Detected
06	47 Worth Street	Basement	No Structure Detected
07	-	Field Blank	Not Analyzed
08	-	Field Blank	Not Analyzed
09	53 Worth Street	5 th Floor	No Structure Detected
10	53 Worth Street	4 th Floor	No Structure Detected
11	53 Worth Street	3 rd Floor	No Structure Detected
12	53 Worth Street	2 nd Floor	No Structure Detected
13	53 Worth Street	1 st Floor	No Structure Detected
14	53 Worth Street	Basement	No Structure Detected
15	53 Worth Street	Sub-Basement	No Structure Detected
16	-	Field Blank	Not Analyzed
17	-	Field Blank	Not Analyzed
18	57 Worth Street	10 th Floor	No Structure Detected
19	57 Worth Street	8 th Floor	No Structure Detected
20	57 Worth Street	7 th Floor	No Structure Detected

EPA permissible Level is 70 Structures/mm²



Warren & Panzer Engineers, P.C.
 228 East 45th Street
 New York, New York 10017
 Tel. (212) 922-0077
 Fax (212) 922-0630

CLIENT: New York Law School

LOCATIONS: 47 Worth Street, 53 Worth Street
 57 Worth Street, 240 Church Street
 New York, NY

Ambient Air Sampling Results

SAMPLE IDENTIFICATION NUMBER	BUILDING ADDRESS	LOCATION	LABORATORY ANALYSIS RESULTS
			Transmission Electron Microscopy (TEM)
21	57 Worth Street	6 th Floor	No Structure Detected
22	57 Worth Street	5 th Floor	No Structure Detected
23	57 Worth Street	4 th Floor	No Structure Detected
24	57 Worth Street	3 rd Floor	No Structure Detected
25	57 Worth Street	Basement	No Structure Detected
26	57 Worth Street	Sub-Basement	No Structure Detected
27	57 Worth Street	9 th Floor	No Structure Detected
28	57 Worth Street	2 nd Floor	No Structure Detected
29	57 Worth Street	Mezzanine	No Structure Detected
30	57 Worth Street	1 st Floor	1.0 Structure/mm ²
31	240 Church Street	4 th Floor	No Structure Detected
32	240 Church Street	3 rd Floor	No Structure Detected
33	240 Church Street	2 nd Floor	No Structure Detected
34	240 Church Street	1 st Floor	No Structure Detected
35	240 Church Street	Basement	No Structure Detected
36	-	Field Blank	Not Analyzed
37	-	Field Blank	Not Analyzed

EPA permissible Level is 70 Structures/mm²