

NOTE: THESE RESULTS ARE NOT FOR
THE BUILDING ABOVE GROUND @
77 MURRAY BUT FOR SUBWAY STATION AREAS
NEAR ~~BELOW~~ 77 MURRAY

Address: 77 MURRAY ST. SEE ATT'Y
LTR. FROM
NYCTA

Bulk Samples
PLM

(Yes)

Number

Number

ACM
Tested

53

0

NO RESULT
TEC. 243-45

TA REVERTING (BASED
ON "TW" ETC. CODE) IN
ATL LAB RESULTS

Air Samples

PCM

Number of Samples Collected (≤ 0.01 f/cc) _____

Number of Samples Collected (>0.01 f/cc) _____

TEM

Number of Samples Collected (≤ 70 s/mm²) _____

Number of Samples Collected (>70 s/mm²) _____

INTERIOR DEBRIS - INDICATES YES
GENERAL CLEAN-UP - YES
ACM CLEANED

NOTE: THESE RESULTS ARE NOT FOR
THE BUILDING ABOVE GROUND @
77 MURRAY BUT FOR SUBWAY STATION AREA
NEAR ~~86~~ 77 MURRAY

Address: 77 MURRAY ST. SEE ATT'Y
LTR. FROM
NYCTA

Bulk Samples
PLM

☒ Yes

☐ No

Number of Negative ($\leq 1\%$) Samples

53

Number of Positive ($> 1\%$) Samples

0

NO RESULT INDICATED $\geq 1\%$. MTA REVERTING (BASED
TEL. 212-548-4581) RE DESIGNATION OF "TW" ETC. CODES IN
ATL LAB RESULTS.

Air Samples

☐ Yes

☒ No

PCM

Number of Samples Collected (≤ 0.01 f/cc) _____

Number of Samples Collected (> 0.01 f/cc) _____

TEM

Number of Samples Collected (≤ 70 s/mm²) _____

Number of Samples Collected (> 70 s/mm²) _____

INTERIOR DEBRIS - INDICATED YES

GENERAL CLEAN-UP - YES

ACM CLEANUP