NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other ASAP

PROJECT INFORMATION

77553 43/49 39761-84809

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	PS 68Q		4a. Air Sampler: Z. KOWALSKI / R. FISHMAN	HP 104
	2a. Project Address: 103-22 99TH ST, QUEENS	3a. Task #		

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
5.15.02		Cassette/Filter Manufacture:	Cassette/Filter Manufacture: MIXII	a. ☐ Background	c. ☐ Abatement / f. ☐ Environmental
		Lot #:	Lot #: 01205916-058	b. ☐ Pre-Abate	d. ☐ Post-Abate / g. ☒ Ambient / e. ☐ OSHA / h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank Open 30 sec									
02				Field Blank Open 30 sec									
03	874932			BSMT Classroom #1 - MIDDLE SECTION	1934	2302	208	9.0	9.0	9	1872		
04	874930			BSMT Classroom #2 - center area	1936	2303	207	9.0	9.0	9	1863		
05	874991			BSMT Room #11 custodian office middle section	1938	2305	207	9.0	9.0	9	1863		
06	874926			BSMT Room #4 - MEDICAL unit	1940	2306	206	9.0	9.0	9	1854		
07	874996			BSMT Room #5 - office	1942	2307	205	9.0	9.0	9	1845		
08	874990			BSMT Room #13 - classroom - 5' in front of CHALK BOARD	1943	2309	206	9.0	9.0	9	1854		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I R. FISHMAN	RRly	05-16-02	2:00
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRly	5.16.02	6:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Y. EFSTATHIOU

27. Result To: _____
Beeper/Phone #'s _____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_00301654 3

NYC-WTC_000207826

VATC ASSOCIATES INC.

7753

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 8

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other ASAP

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	P3 65Q			HP 104
	2a. Project Address 103-22 99th St, Q	3a. Task #	4a. Air Sampler: Z. KOWALSKI / R. FISHMAN	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture MMI / Lot # 01205916-058	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other
5.15.02				

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
09	874943			BSMT Rm #14 - classroom middle section - 10' from chalk board	1945	2310	205	9.0	9.0	9.0	1845		
10	874994			BSMT Room #19 - classroom by center	1947	2311	204	9.0	9.0	9.0	1836		
11	874968			BSMT Room #16 - office by center (special educat)	1949	2312	203	9.0	9.0	9.0	1827		
12	874928			BSMT Room #18 classroom by center	1950	2314	204	9.0	9.0	9.0	1836		
13	874980			BSMT Room #20 classroom 15' from middle of chalk board	1953	2315	202	9.0	9.0	9.0	1818		
14	874498			BSMT Room #23 paint art supply room	1955	2317	202	9.0	9.0	9.0	1818		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	R. FISHMAN	RRuy	05-16-02	2:00
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRuy	5.16.02	6:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Y. EFSTATHIOU

27. Result To: _____
Beeper/Phone #'s _____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_0030165544

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC.

7753

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☑ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other ASAP

PROJECT INFORMATION

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	PS 65Q			HP 104
	2a. Project Address: 103-22 99th St, QT	3a. Task #	4a. Air Sampler: Z. KOWALSKI / R. FISHMAN	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:		
05-15-02		Cassette/Filter Manufacture:	Cassette/Filter Manufacture: MMI	a. ☐ Background	c. ☐ Abatement	f. ☐ Environmental
		Lot #:	Lot # 01205916-058	b. ☐ Pre-Abate	d. ☐ Post-Abate	g. ☑ Ambient
					e. ☐ OSHA	h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
15	874946			BSMT - Room #28 – PTA office	1957	2320	203 ~~1823~~	9.0	9.0	9	1827		
16	874884			1ST FLOOR, main lobby – 20' from pas. elevator	2000	2323	203 ~~1823~~	9.0	9.0	9	1827		
17	874947			1ST FLOOR, GYM – central section	2001	2324	203 ~~1823~~	9.0	9.0	9	1827		
18	874960			1ST FLOOR, CAFETERIA – central section	2003	2325	202	9.0	9.0	9	1818		
19	874999			1ST FLOOR, GENERAL office, within faxmachine	2005	2327	202	9.0	9.0	9	1818		
20	874927			1ST FLOOR, Room # 111 – central section	2006	2328	202	9.0	9.0	9	1818		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I R. FISHMAN	RKy	5/16/02	2:00
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RKy	5.16.02	6:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Y. EFSTATHIOU

27. Result To: _____
Beeper/Phone #'s _____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_0030316545

NYC-WTC_000207828

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

7753

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other ASAP

PROJECT INFORMATION

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	P.S. 65Q			HP104
	2a. Project Address: 103-22, 99St, QUEENS	3a. Task #	4a. Air Sampler: Z. KOWALSKI / R. FISHMAN	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:
05-15-02		Cassette/Filter Manufacture:	Cassette/Filter Manufacture: MMI	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other
		Lot #:	Lot #: 01205916-058	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-21	874894			1ST FLOOR, Room # 117 classroom - middle section	2008	2330	202	9.0	9.0	9	1818		
-22	874955			1ST FLOOR, Room # 118, special education room by center	2010	2331	201	9.0	9.0	9	1809		
-23	874998			1ST FLOOR, Room # 120 classroom, central section	2011	2333	202	9.0	9.0	9	1818		
-24	874951			1ST FLOOR, Room # 127 teacher's lunch RM - 8' from exit	2013	2334	201	9.0	9.0	9	1809		
-25	874997			1ST FLOOR, Room # 134 office, by center	2017	2337	200	9.0	9.0	9	1800		
-26	874954			1ST FLOOR, Room # 128 classroom, 15' from sink	2018	2339	201	9.0	9.0	9	1809		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	R FISHMAN	R Rly	05-16-02	2:00
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRly	5.16.02	6:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Y. EFSTATHIOU

27. Result To: _____
Beeper/Phone #'s _____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_0030165 46

NYC-WTC_000207829

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

7753

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other ASAP

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	P.S. 65Q		Z. KOWALSKI / R. FISHMAN	HP104
	2a. Project Address: 103-22 99ST, QUEENS	3a. Task #	4a. Air Sampler:	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☑ TEM (0.45 micron MCE) Cassette/Filter Manufacture MMI / Lot # 01205916-058	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other
05-15-02				

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-27	874890			1ST FLOOR, Room #129 classroom, central section	2020	2042	202	9.0	9.0	9	1818		
-28	874906			2nd FLOOR, Room #K201 -classroom, central section	2024	2345	201	9.0	9.0	9	1809		
-29	874992			2nd FLOOR, Room #K203 -classroom, central section	2026	2346	200	9.0	9.0	9	1800		
-30	874914			2nd FLOOR, Room #K204 -classroom, 15' from chalk board	2028	2351	203	9.0	9.0	9	1827		
-31	874888			2nd FLOOR, Room #205 -GUIDANCE Room - by centre	2030	2352	202	9.0	9.0	9	1818		
-32	874886			2nd FLOOR, Room #221 -classroom, middle section	2032	2353	201	9.0	9.0	9	1809		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	R. FISHMAN	RRuy	05-16-02	2:00
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-JFM	23. Date:	24. Time:
a. Analyzed By: RRuy	5/16/02	6:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Y. EFSTATHIOU

27. Result To: _____
Beeper/Phone #'s _____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_00301654?

NYC-WTC_000207830

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

7753

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other ASAP

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	P.S. 65Q			HP 104
	2a. Project Address: 103-22 99St, QUEENS	3a. Task #	4a. Air Sampler: Z. KOWALSKI / R. FISHMAN	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		
05-15-02		Cassette/Filter Manufacture:	Cassette/Filter Manufacture: MMI	a. ☐ Background	c. ☐ Abatement	f. ☐ Environmental
		Lot #:	Lot #: 01205916-058	b. ☐ Pre-Abate	d. ☐ Post-Abate	g. ☒ Ambient
					e. ☐ OSHA	h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-33	874922			2nd FLOOR, Room #222 classroom, by center	2033	2354	201	9.0	9.0	9	1809		
-34	874929			2nd FLOOR, Room #212 classroom, 6' in front of teacher desk	2035	2357	202	9.0	9.0	9	1818		
-35	874920			2nd FLOOR, Room #216 classroom, by center	2036	2359	203	9.0	9.0	9	1827		
-36	874909			2nd FLOOR, Room #223 classroom, on the rug area	2039	2400	201	9.0	9.0	9	1809		
-37	874883			2nd FLOOR, Room #229 staff developer	2040	2402	202	9.0	9.0	9	1818		
-38	874973			2nd FLOOR, Room #232 classroom	2042	2403	201	9.0	9.0	9	1809		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	R. FISHMAN	RKW	05-16-02	2:00
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RKW	5/16/02	6:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Y. EFSTATHIOU

27. Result To: _____
Beeper/Phone #'s _____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_0030165548

NYC-WTC_000207831

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other ASAP

PROJECT INFORMATION

1. Client:	2. Project Name / 2a. Project Address	3. Project # / 3a. Task #	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC BOE	P.S. 65Q / 103-22 99St, QUEENS		Z. KOWALSKI / R. FISHMAN	HP104

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:		
05-15-02		Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: MMI Lot#: 01205916-058	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-39	874938			2nd FLOOR, Room #237 - CLASSROOM, 18' from chalk board	2043	2404	201	9.0	9.0	9.0	1809		
-40	814895			2nd FLOOR, Room #233 - Library - 20' from entrance	2045	2405	200	9.0	9.0	9.0	1800		
-41	874939			2nd FLOOR, Room #218 - CLASSROOM, 20' from chalk board	2049	2410	201	9.0	9.0	9.0	1809		
-42	874932			2nd FLOOR, Room #215 - classROOM, 12' from chalk board	2051	2411	200	9.0	9.0	9.0	1800		
-43	874916			2nd FLOOR, Room #214 - classROOM, 15' from chalk board	2053	2413	200	9.0	9.0	9.0	1800		
-44	874972			2nd FLOOR, Room #211 - classROOM, 15' from chalk board	2054	2415	201	9.0	9.0	9.0	1809		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I R. FISHMAN	RRuy	05-16-02	2:00
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC TEM	23. Date:	24. Time:
a. Analyzed By: RRuy	5.16.02	6:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Y. EFSTATHIOU

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_0030316549

NYC-WTC_000207832

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other ASAP

OJECT INFORMATION

Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	P.S. 65Q			
	2a. Project Address 103-22 99st, QUEENS	3a. Task #	4a. Air Sampler: Z. KOWALSKI / R. FISHMAN	HP 104

Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:	
5-15-02		Cassette/Filter Manufacture	Cassette/Filter Manufacture MMI	a. ☐ Background	c. ☐ Abatement / f. ☐ Environmental
		Lot #	Lot # 01205916-058	b. ☐ Pre-Abate	d. ☐ Post-Abate / g. ☑ Ambient
					e. ☐ OSHA / h. ☐ Other

ILY AIR SAMPLE RECORD

Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-45	874931			Roof, 35' from street middle section	2057	2417	200	9.0	9.0	9	1800		
-46				Sealed Blank									
-47				FIELD BLANK - open 30sec									
-48				FIELD BLANK - open 30 sec.									
-49				FIELD BLANK - open 30 sec									

AIN OF CUSTODY

Relinquished By:	19. Received By:	20. Date:	21. Time:
R. FISHMAN	R Ruy	05-16-02	2:00

ATC Project Manager: Y. EFSTATHIOU

27. Result To: _____
Beeper/Phone #'s _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: R Ruy	5-16-02	6:00
b. QC By:		
c. Lab Batch #:		

28. Comments:

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_00301655O

NYC-WTC_000207833