NYC 9/11 Public Portal Document

09/30/2002 08:20 FAX 212 353 8306 ATC 026

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334
7:58

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	TVOCs (ppm)	Window Conditions
Ext. Main Entry		67.9	65.0	483	2		~~Open Windows~~ ~~Closed Windows~~ ~~No Windows~~
Main Lobby	12	66.6	65.8	553	2		Open Windows / Closed Windows / No Windows ✓
Gym	86	67.7	67.8	717	1		Open Windows / Closed Windows ✓ / No Windows
Staircase B 1st fl.	2	66.8	68.1	533	1		Open Windows / Closed Windows / No Windows ✓
Cafeteria	127	67.4	68.2	593	1		Open Windows ✓ / Closed Windows / No Windows
Kitchen	5	79.2	71.1	803	1		Open Windows / Closed Windows / No Windows ✓
1st fl. Hallway	7	71.5	69.4	736	1		Open Windows / Closed Windows / No Windows ✓
General off.	3	71.7	67.6	686	1		Open Windows / Closed Windows / No Windows ✓
RIII	0	72.2	65.9	639	1		Open Windows / Closed Windows / No Windows ✓
Guideline levels ASHRAE/AIHA		**69 – 76°F/winter 73 -79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medwell **Date:** 9-27-02

CITY_21MC100_00403596?

NYC-WTC_000207838

NYC 9/11 Public Portal Document

09/30/2002 08:21 FAX 212 353 8308 ATC

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334

8:39

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	VOC (ppm)	Window Conditions
R 117	28	71.7	63.8	590	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R 118	0	71.3	63.0	562	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R 120 & 121	24	70.8	62.5	526	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
1st. fl. Hallway	0	70.9	62.4	559	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R 127	2	71.4	63.1	629	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R 134	1	71.5	62.3	583	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R 128	30	71.2	62.2	593	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R 129	27	71.0	62.2	599	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
Staircase E 1st. fl.	0	71.1	62.3	542	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Guideline levels ASHRAE/AIHA		**69 – 76°F/winter 73 -79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M Medinets Date: 9-27-02

CITY_21MC100_004035968

☑ 027

NYC-WTC_000207839

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334

9:17

Location	Floor	Temperature (°F)	Relative humidity (%)	Carbon dioxide (ppm)	Carbon monoxide (ppm)	Dust (mg/m³)	Window condition
Staircase D 1st fl.	0	71.0	62.7	571	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
2nd fl. Hallway	1	70.4	62.0	578	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R 218	17	70.9	62.7	653	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R 215	16	71.0	62.8	617	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R 214	23	71.0	63.3	846	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R 211	17	71.2	63.4	677	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
2nd fl. Hallway	1	71.2	62.7	555	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Staircase B 2nd fl.	1	71.2	63.4	643	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R 201	15	71.1	62.6	636	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
Guideline levels ASHRAE/AIHA		**69 – 76°F/winter 73 -79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medwed **Date:** 9-27-02

CITY_21MC100_0040359969

NYC-WTC_000207840

NYC 9/11 Public Portal Document

205C

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334

9:58

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (PPM)	Carbon Monoxide (PPM)	VOC's (ppm)	Window Conditions
R203	14	71.6	62.4	624	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R204	16	72.0	62.8	592	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R205	5	72.5	62.2	581	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R221	22	72.7	60.1	653	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R222	20	72.4	60.2	759	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R212	19	72.2	60.0	702	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R216	22	72.1	60.5	768	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R223	15	71.7	60.2	713	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R229	0	71.7	59.4	666	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Guideline levels ASHRAE/AIHA		69 – 76°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	1 ppm	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medwed **Date:** 9-27-02

09/30/2002 08:22 FAX 212 353 8306 ATC ☑029

CITY_21MC100_00403597O

NYC-WTC_000207841

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334
10:39

Location	Floor	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	PM10 (ppm)	Ventilation conditions
R232	1	71.9	59.3	616	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R237	17	72.0	60.5	721	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
R233	15	71.5	60.0	694	2		☐ Open Windows ☑ Closed Windows ☐ No Windows
Staircase E 2nd. fl.	0	71.7	60.0	546	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Staircase E Nssu	0	71.8	60.5	636	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Nssu Hallway	0	71.7	59.5	681	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R28	10	71.2	56.5	827	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R20	11	71.5	56.6	820	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R18	13	70.8	56.3	893	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Guideline levels ASHRAE/AIHA		**69–76°F/winter 73–79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air-quality guidelines.

Signature: M. Medinets **Date:** 9-27-02

09/30/2002 08:23 FAX 212 353 8306 ATC 030

CITY_21MC100_00403597l

NYC-WTC_000207842

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334

11:27

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	TVOC's (ppm)	Window Conditions
R16	1	71.1	57.4	846	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R19	10	71.3	58.1	989	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Staircase C Base	0	71.3	60.1	757	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R14	17	71.2	57.7	819	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Base Hallway	0	71.5	57.1	796	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Staircase B Base	0	71.6	57.2	786	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R1	30	71.9	58.7	1005	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R2	0	71.9	58.0	783	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
R4	1	72.0	56.6	705	2		☐ Open Windows ☐ Closed Windows ☑ No Windows
Guideline levels ASHRAE/AIHA		**69 – 76°F/winter 73 -79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medinets **Date:** 9-27-02

09/30/2002 08:23 FAX 212 353 8306 ATC 031

CITY_21MC100_00403597 2

NYC-WTC_000207843

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-033V

12:09

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	VOC (ppm)	Ventilation Conditions
R13	1	72.0	55.6	705	2		☐ Open Windows ☐ Closed Windows ☒ No Windows
R5	0	71.8	55.3	686	2		☐ Open Windows ☐ Closed Windows ☒ No Windows
Staircase A Roof	0	72.1	55.6	684	2		☐ Open Windows ☐ Closed Windows ☒ No Windows
Ext. Playground		72.4	61.6	583	2		☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
Guideline levels ASHRAE/AIHA		69 – 76°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	1 ppm	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medines **Date:** 9-27-02

09/30/2002 08:24 FAX 212 353 8306 ATC 032

CITY_21MC100_0040359 73

NYC-WTC_000207844

NYC 9/11 Public Portal Document

09/30/2002 08:24 FAX 212 353 8308 ATC 033

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-033Y

12:51

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	VOC's (ppm)	Window Condition
Ext. Main Entry		70.4	74.8	430	1		☐ Open Windows ☐ Closed Windows ☐ No Windows
Main Lobby	1	70.5	74.8	441	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Gym	0	69.2	59.2	489	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
Staircase to 1st. fl.	1	69.0	59.5	483	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Cafeteria	97	69.8	59.4	758	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
Kitchen	4	72.2	59.9	875	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
1st. fl. Hallway	0	73.8	60.9	902	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
General office	4	73.1	59.5	732	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Elll	0	73.8	60.3	687	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Guideline levels ASHRAE/AIHA		**69 – 76°F/winter 73 -79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medinets **Date:** 9-27-02

CITY_21MC100_0040359974

NYC-WTC_000207845

NYC 9/11 Public Portal Document

09/30/2002 08:25 FAX 212 353 8308 ATC 034

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334

13:36

Description	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	VOC (ppm)	Ventilation conditions
R117	27	73.6	59.4	734	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R118	0	73.7	59.3	696	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R120 & 121	24	73.7	58.9	703	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
1st floor hallway	0	73.3	57.8	739	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R127	9	73.3	57.7	794	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
R134	1	73.5	58.0	804	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R128	30	73.6	57.8	788	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
R129	27	73.8	57.5	736	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
Staircase E 1st fl.	0	73.8	56.6	678	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Guideline levels ASHRAE/AIHA		**69 – 76°F/winter 73 -79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medwed **Date:** 9-27-02

CITY_21MC100_00403597S

NYC-WTC_000207846

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334

14:18

Location	Occup.	Temperature (°F)	Relative humidity (%)	Carbon dioxide (ppm)	Carbon monoxide (ppm)	VOC (ppm)	Windows condition
Staircase D 1st. fl.	0	73.1	54.4	606	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
2nd fl. Hallway	0	71.2	57.0	604	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R218	17	71.6	60.4	700	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
R215	19	71.9	60.1	733	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
R214	22	71.8	59.9	739	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
R211	17	71.9	60.5	843	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
2nd fl. Hallway	2	71.8	60.3	749	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Staircase B 2nd fl.	0	71.9	60.7	957	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
~~2nd fl.~~ R201 ~~Hallway~~	14	71.6	60.2	796	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
Guideline levels ASHRAE/AIHA		**69 – 76°F/winter 73 -79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medwed **Date:** 9-27-02

CITY_21MC100_00403597G

NYC-WTC_000207847

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334
15:01

Location	People	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	VOC (ppm)	Windows Conditions
R203	0	72.0	60.9	719	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
R204	16	72.2	64.1	691	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
R205	7	72.7	64.6	660	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R221	0	72.8	62.6	693	1		☐ Open Windows ☑ Closed Windows ☐ No Windows
R222	2	72.8	64.4	739	1		☑ Open Windows ☐ Closed Windows ☐ No Windows
R212	0	72.7	62.1	719	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R216	1	72.6	59.8	708	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R223	0	72.2	59.9	692	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R229	1	72.3	62.4	580	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Guideline levels ASHRAE/AIHA		**69 – 76°F/winter 73 -79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medinets **Date:** 9-27-02

09/30/2002 08:26 FAX 212 353 8306 ATC ☑036

CITY_21MC100_00403597

NYC-WTC_000207848

NYC 9/11 Public Portal Document

09/30/2002 08:28 FAX 212 353 8306 ATC 037

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334

15:41

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	VOC (ppm)	Ventilation Conditions
R232	0	72.5	63.0	599	1		☐ Open Windows ☐ Closed Windows ☒ No Windows
R237	0	72.5	63.2	637	1		☐ Open Windows ☒ Closed Windows ☐ No Windows
R233	0	72.3	62.1	540	1		☐ Open Windows ☒ Closed Windows ☐ No Windows
Staircase E 2nd fl.	0	72.3	62.2	546	1		☐ Open Windows ☐ Closed Windows ☒ No Windows
Staircase E Bsmt	0	72.3	62.5	562	1		☐ Open Windows ☐ Closed Windows ☒ No Windows
Bsmt Hallway	0	72.1	60.6	599	1		☐ Open Windows ☐ Closed Windows ☒ No Windows
R28	0	71.9	59.4	649	1		☐ Open Windows ☐ Closed Windows ☒ No Windows
R20	1	70.9	58.0	546	1		☐ Open Windows ☐ Closed Windows ☒ No Windows
R18	0	71.3	58.3	589	1		☐ Open Windows ☐ Closed Windows ☒ No Windows
Guideline levels ASHRAE/AIHA		69 – 76°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	1 ppm	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medinets Date: 9-27-02

CITY_21MC100_00403597B

NYC-WTC_000207849

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-033Y
16:20

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	VOC (ppm)	Weather conditions
R16	0	71.3	58.6	600	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R19	1	71.3	59.1	599	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Staircase C B5th	0	71.4	59.4	669	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R14	1	71.5	59.9	719	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
B5th Hallway	0	71.7	60.0	695	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Staircase B B5th	0	71.9	59.4	667	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R1	0	71.9	59.7	706	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R2	2	72.1	59.3	668	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R4	1	72.1	59.1	666	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Guideline levels ASHRAE/AIHA		69 – 76°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	1 ppm	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medines Date: 9-27-02

09/30/2002 08:27 FAX 212 353 8306 ATC ☑038

CITY_21MC100_00403597

NYC-WTC_000207850

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 650/103-32 99th St, Queens DATE 9-27-02 PROJECT NO. 19125-0334

16:57

Location	People	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	VOC (ppm)	Window Conditions
R13	2	72.1	59.9	647	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
R5	1	72.1	58.8	629	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Staircase # Bsmt	0	72.7	60.8	639	1		☐ Open Windows ☐ Closed Windows ☑ No Windows
Ext. Playground		72.3	76.3	467	1		☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
							☐ Open Windows ☐ Closed Windows ☐ No Windows
Guideline levels ASHRAE/AIHA		**69 – 76°F/winter 73 -79°F/summer**	**30-60%**	**Outdoor level + 700 ppm**	**9 ppm**	**1 ppm**	

Comments: _____

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: M. Medwed **Date:** _____

09/30/2002 08:28 FAX 212 353 8308 ATC 039

CITY_21MC100_00403598O

NYC-WTC_000207851