



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client NYC - BOE 2 Project Name PS 126 M 3 Project # 14584 08 4 Project Monitor H. Antonyan 4c Rotameter Number HP-128

2a Project Address 20 Catherine St NY NY 3a Task # 72 4a Air Sampler H. Antonyan

5 Date 8/21/02 6 Abatement Location Throughout the building & Roof 7 ☐ PCM (0.8 micron MCE) 8 ☒ TEM (0.45 micron MCE) 9 Type c ☐ Abatement ☐ Environmental

Cassette/Filter Manufacture MMI Cassette/Filter Manufacture MMI Lot # 02106916

a ☐ Background d ☐ Post Abate g ☒ Ambient
b ☐ Pre Abate e ☐ OSHA h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15	16	17
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg	Total Air Vol (liters)	# Fibers/Fields Minus Blank	Fiber Conc F/CC
<u>18</u>				<u>Field Blank</u>									
<u>19</u>				<u>Field Blank</u>									
<u>01</u>	<u>1</u>			<u>1st floor lobby</u>	<u>06 31</u>	<u>10 31</u>	<u>240</u>	<u>8 0</u>	<u>8 0</u>	<u>8 0</u>	<u>1920</u>		
<u>02</u>	<u>1</u>			<u>Cafeteria</u>	<u>06 36</u>	<u>10 37</u>	<u>241</u>	<u>8 0</u>	<u>8 0</u>	<u>8 0</u>	<u>1928</u>		
<u>03</u>	<u>1</u>			<u>Auditorium</u>	<u>06 42</u>	<u>10 42</u>	<u>240</u>	<u>8 0</u>	<u>8 0</u>	<u>8 0</u>	<u>1920</u>		
<u>04</u>	<u>1</u>			<u>1st floor Hallway</u>	<u>06 47</u>	<u>10 50</u>	<u>243</u>	<u>8 0</u>	<u>8 0</u>	<u>8 0</u>	<u>1944</u>		
<u>05</u>	<u>1</u>			<u>1st floor Classroom # 125</u>	<u>06 51</u>	<u>10 53</u>	<u>242</u>	<u>8 0</u>	<u>8 0</u>	<u>8 0</u>	<u>1936</u>		
<u>06</u>	<u>1</u>			<u>1st floor Classroom # 123</u>	<u>06 57</u>	<u>11 00</u>	<u>243</u>	<u>8 0</u>	<u>8 0</u>	<u>8 0</u>	<u>1944</u>		

CHAIN OF CUSTODY

18 Relinquished By I. H. Antonyan 19 Received By JD 20 Date 8/21/02 21 Time 17 00

26 ATC Project Manager _____ 27 Result To _____
Beeper/Phone # s _____

LAB INFORMATION (ATC ELAP # 10879 ATC NVLAP # 1187)

22 Lab Name ATC-TEMI 23 Date 8/21/02 24 Time 10 45

a Analyzed By MMI b QC By _____ c Lab Batch # _____

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
 PCM NIOSH 7400A
 TEM AHERA

28 Comments _____

WHITE File

YELLOW Client/Report

PINK Lab

GOLDENROD Field

NY 1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client <u>NYC BOE</u>		2 Project Name <u>PS 126 M</u>		3 Project # <u>14584-0872</u>		4 Project Monitor <u>H Antonian</u>		4c Rotameter Number <u>114-12</u>	
		2a Project Address <u>80 Catherine St NY, NY</u> <u>Jacob Rius Community School</u>		3a Task #		4a Air Sampler			
5 Date <u>8/21/02</u>		6 Abatement Location <u>Throughout the building & Roof</u>		7 ☐ PCM (0.8 mic o MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 m ro MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>		9 Type a ☐ Background d ☐ Post Abate b ☐ Pre Abate e ☐ OSHA	
								f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
20				Field Blank <u>Sealed Blank</u>									
				Field Blank									
07	1			<u>2nd floor Hallway</u>	07 02	11 05	243	8 0	8 0	8 0	1944		
08	1			<u>2nd floor Classroom # 203</u>	07 06	11 07	241	8 0	8 0	8 0	1928		
09	1			<u>2nd floor Classroom # 237</u>	07 11	11 11	240	8 0	8 0	8 0	1920		
10			1	<u>Roof (Central)</u>	07 17	11 19	242	8 0	8 0	8 0	1936		
11			1	<u>Outside of Main Entrance</u>	07 25	11 28	243	8 0	8 0	8 0	1944		
12	1			<u>3rd floor Hallway</u>	12 00	16 00	240	8 0	8 0	8 0	1920		

CHAIN OF CUSTODY

18 Relinquished By <u>I H Lef</u>		19 Received By <u>JR</u>		20 Date <u>8/21/02</u>	21 Time <u>1700</u>
II					
III					
26 ATC Project Manager		27 Result To _____ Beeper/Phone # s _____			

LAB INFORMATION (ATC ELAP # 10879 ATC NVLAP # 1187)

22 Lab Name <u>ATC - TE, "</u>		23 Date <u>8/21/02</u>	24 Time <u>1045</u>	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079	
a Analyzed By <u>Kelly</u>					
b QC By					
c Lab Batch #				28 Comments	
26 ATC Project Manager		27 Result To _____ Beeper/Phone # s _____			

WHITE File

YELLOW Client/Report

PINK Lab

GOLDENROD Field

NY 1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client NYC - BOE
 2 Project Name PS 126M / 1A 293
 3 Project # 14584-0872
 4 Project Monitor
 2a Project Address 80 Catherine St NYC
 3a Task #
 4a Air Sampler H Antonyan
 4c Rotameter Number HP 128
 5 Date 8/21/02
 6 Abatement Location throughout the building
 7 ☐ PCM (0.8 micron MCE)
 Cassette/Filter Manufacture
 Lot #
 8 ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture MMI
 Lot # 02106916
 9 Type
 a ☐ Background c ☐ Abatement
 b ☐ Pre Abate d ☐ Post Abate
 e ☐ OSHA f ☐ Environmental
 g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg	15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
				Field Blank							1		
				Field Blank									
13		1		3rd floor Classroom # 319	12 04	16 04	240	8 0	8 0	2 0	1920		
14		1		3rd floor Classroom # 325	12 07	16 07	240	8 0	8 0	2 0	1920		
15		1		4th floor Hallway	12 11	16 12	241	8 0	8 0	3 0	1928		
16		1		4th floor Classroom # 443	12 14	16 15	241	8 0	8 0	2 0	1928		
17		1		4th floor Classroom # 429	12 17	16 17	240	8 0	8 0	2 0	1920		

CHAIN OF CUSTODY

18 Relinquished By I H A L
 II
 III
 26 ATC Project Manager
 19 Received By JD
 20 Date 8/21/02
 21 Time 1700
 27 Result To
 Beeper/Phone # s

LAB INFORMATION (ATC ELAP # 10879 ATC NVLAP # 1187)

22 Lab Name ATC-7E
 a Analyzed By RLG
 b QC By
 c Lab Batch #
 23 Date 8/21/02
 24 Time 1545
 25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 Analysis Methodology
 PCM NIOSH 7400A
 TEM AHERA
 28 Comments

WHITE File YELLOW Client/Report

PINK Lab GOLDENROD Field

NY 1 (1/01)