



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client NYC - BOE 2 Project Name PS 126 M 3 Project # 14584 4 Project Monitor H. Antonyan 4c Rotameter Number HP-128

2a Project Address 20 Catherine St NY NY 3a Task # 72 4a Air Sampler H. Antonyan

5 Date 8/21/02 6 Abatement Location Throughout the building & Roof 7 ☐ PCM (0.8 m cron MCE) 8 ☒ TEM (0.45 m cron MCE) 9 Type c ☐ Abatement f ☐ Environmental

Cassette/Filter Manufacture _____ Cassette/Filter Manufacture MMI a ☐ Background d ☐ Post Abate g ☒ Ambient

Lot # _____ Lot # 02106916 b ☐ Pre Abate e ☐ OSHA h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location	13 Time (24 hrs clock)	14 Flow Rate (L/min)	15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA 12b OWA 12c Sample Coordinates	13a Start 13b End 13c Total	14a Start 14b End 14b Avg			
<u>18</u>		<u>Field Blank</u>					
<u>19</u>		<u>Field Blank</u>					
<u>01</u>	<u>1</u>	<u>1st floor lobby</u>	<u>06 31 10 31 240</u>	<u>8 0 8 0 8 0</u>	<u>1920</u>		
<u>02</u>	<u>1</u>	<u>Cafeteria</u>	<u>06 36 10 37 241</u>	<u>8 0 8 0 8 0</u>	<u>1928</u>		
<u>03</u>	<u>1</u>	<u>Auditorium</u>	<u>06 42 10 42 240</u>	<u>8 0 8 0 8 0</u>	<u>1920</u>		
<u>04</u>	<u>1</u>	<u>1st floor Hallway</u>	<u>06 47 10 50 243</u>	<u>8 0 8 0 8 0</u>	<u>1944</u>		
<u>05</u>	<u>1</u>	<u>1st floor Classroom # 125</u>	<u>06 51 10 53 242</u>	<u>8 0 8 0 8 0</u>	<u>1936</u>		
<u>06</u>	<u>1</u>	<u>1st floor Classroom # 123</u>	<u>06 57 11 00 243</u>	<u>8 0 8 0 8 0</u>	<u>1944</u>		

CHAIN OF CUSTODY

18 Relinquished By I H. Antonyan 19 Received By JD 20 Date 8/21/02 21 Time 17 00

26 ATC Project Manager _____ 27 Result To _____
Beeper/Phone # s _____

LAB INFORMATION (ATC ELAP # 10879 ATC NVLAP # 1187)

22 Lab Name ATC - TEM 23 Date 8/21/02 24 Time 10 45

a Analyzed By I. H. Antonyan b QC By _____ c Lab Batch # _____

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
 PCM NIOSH 7400A
 TEM AHERA

28 Comments _____

WHITE File

YELLOW Client/Report

PINK Lab

GOLDENROD Field

NY 1 (1/01)

CITY_21MC100_003016986



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

8730

1 Client <u>NYC-BOE</u>		2 Project Name <u>PS 126 M</u>		3 Project # <u>14584-0872</u>		4 Project Monitor		4c Rotameter Number <u>11P-1's</u>	
		2a Project Address <u>80 Catherine St NY, NY</u> <u>Jacob Rius Community School</u>		3a Task #		4a Air Sampler <u>H Anderson</u>			
5 Date <u>2/21/02</u>		6 Abatement Location <u>Throughout the building & Roof</u>		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>		9 Type a ☐ Background d ☐ Post Abate b ☐ Pre Abate e ☐ OSHA	
								f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location		12c Sample Coordinates	13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA		13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
20				Field Blank <u>Sealed Blank</u>									
				Field Blank									
07	1			<u>2nd floor Hallway</u>	07 02	11 05	243	8 0	8 0	8 0	1944		
08	1			<u>2nd floor Classroom # 203</u>	07 06	11 07	241	8 0	8 0	8 0	1928		
09	1			<u>2nd floor Classroom # 237</u>	07 11	11 11	240	8 0	8 0	8 0	1920		
10			1	<u>Roof (Central)</u>	07 17	11 19	242	8 0	8 0	8 0	1936		
11			1	<u>Outside of Main Entrance</u>	07 25	11 28	243	8 0	8 0	8 0	1944		
12	1			<u>3rd floor Hallway</u>	12 00	16 00	240	8 0	8 0	8 0	1920		

CHAIN OF CUSTODY

18 Relinquished By		19 Received By		20 Date	21 Time
I <u>ATC</u>				<u>2/21/02</u>	
II		<u>JD</u>		<u>2/21/02</u>	<u>1700</u>
III					
26 ATC Project Manager				27 Result To _____ Beeper/Phone # s _____	

LAB INFORMATION (ATC ELAP # 10879 ATC NVLAP # 1187)

22 Lab Name <u>ATC-TE, "</u>		23 Date	24 Time	25 Microscope Make/Senal # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079	
a Analyzed By <u>WJL</u>		<u>2/21/02</u>	<u>1045</u>		
b QC By					
c Lab Batch #				Analysis Methodology PCM NIOSH 7400A TEM AHERA	
28 Comments					

WHITE File

YELLOW Client/Report

PINK Lab

GOLDENROD Field

NY 1 (1/01)

CITY_21MC100_003016987



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client NYC - BOE
 2 Project Name PS 126M / 1A 293
 2a Project Address 80 Catherine St NY NY
 3 Project # 14584-0812
 3a Task # _____
 4 Project Monitor H. Antonyan
 4c Rotameter Number HP-128
 5 Date 8/21/02
 6 Abatement Location throughout the building
 7 ☐ PCM (0.8 micron MCE)
 Cassette/Filter Manufacture _____
 Lot # _____
 8 ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture MMI
 Lot # 02106916
 9 Type
 a ☐ Background c ☐ Abatement
 b ☐ Pre Abate d ☐ Post Abate
 e ☐ OSHA f ☐ Environmental
 g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location		13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14c Avg		
				Field Blank								
				Field Blank								
13		1		3rd floor Classroom # 319	12 04	16 04	240	8 0	8 0	8 0	1920	
14		1		3rd floor Classroom # 325	12 07	16 07	240	8 0	8 0	8 0	1920	
15		1		4th floor Hallway	12 11	16 12	241	8 0	8 0	3 0	1928	
16		1		4th floor Classroom # 443	12 14	16 15	241	8 0	8 0	8 0	1928	
17		1		4th floor Classroom # 429	12 17	16 17	240	8 0	8 0	8 0	1920	

CHAIN OF CUSTODY

18 Relinquished By I H. Antonyan
 II JP
 III _____
 19 Received By _____
 20 Date 8/21/02
 21 Time 1700
 26 ATC Project Manager _____
 27 Result To _____
 Beeper/Phone # s _____

LAB INFORMATION (ATC ELAP # 10879 ATC NVLAP # 1187)

22 Lab Name ATC-7E
 a Analyzed By R. G. G.
 b QC By _____
 c Lab Batch # _____
 23 Date 8/21/02
 24 Time 16 45
 25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 Analysis Methodology
 PCM NIOSH 7400A
 TEM AHERA

WHITE File

YELLOW Client/Report

PINK Lab

GOLDENROD Field

NY 1 (1/01)

CITY_21MC100_003016988