


**SAFETY ENVIRONMENTAL
CO. OF N.Y. INC.**

(718) 390-0914
Fax (718) 390-0915

33 Clinton Avenue
Staten Island, NY 10301

CLIENT: NYC D.O.T.

SITE: 253 BROADWAY, NEW YORK, NY

RE: ASBESTOS AIR MONITORING AND TESTING IN ROOM 500 & 502

DATE SAMPLE COLLECTED: 9/19/01

DATE SAMPLE ANALYZED: 9/19/01

FILE NO.: 01-137

BATCH #: 9-008

SAMPLE TYPE: AIR QUALITY

CERTIFICATE OF ANALYSIS

Airborne asbestos analysis by NIOSH method no. 7400-phase contrast microscopy New York State ELAP # 11475, American Industrial Hygiene association # 17049. Microscope Type-PCM, Make-Olympus, Model CH-2

SAMPLE NUMBER	SAMPLE LOCATION	TOTAL TIME SAMPLED (MIN)	FLOW RATE (L/Min)	VOLUME (L)	RESULTS FIBERS/ CC
AT-1	RM500 FRONT CUBICLE OFFC	120	15	1800	0.002
AT-2	RM500 CENTER CUBICLE OFFC	120	15	1800	0.004
AT-3	RM500 REAR CUBICLE OFFC	120	15	1800	0.003
AT-4	RECEPTION AREA FR RM502	60	15	900	0.004
AT-5	RM502 MOORE'S OFFICE	60	15	900	0.005
AT-6	REAR OF RM502	60	15	900	0.004
AT-7	RM 500 HOWARD'S OFFICE	60	15	900	0.005
AT-8	RM 500 YOUNG'S OFFICE	60	15	900	0.007
AT-9	CONFERENCE RM500	60	15	900	0.007
AT-10	CORRIDOR OUTSIDE RM502	60	15	900	0.005
AT-11	OFFICE RT OF MOORE RM 502	60	15	900	0.004
AT-12	BACK OFFICE RM502	60	15	900	0.005
AT-13	1 ST RM L BCK CUBICLE RM500	60	15	900	0.007
AT-14	OFFICE RT OF CONF ROOM	60	15	900	0.005

Jane Kozlowski
Laboratory Analyst

Francis O'Neil M.S., RPH
Laboratory Director

Environmental Engineering Consultant • Asbestos, Lead, and Gas Air Monitoring & Testing, Inspections
Project Management • Laboratory Analytical Testing Services • Abatement Design • Phase 1 & 2

CITY_21MC100_006678140