

SciLab Job #: 202051380

Client Name: TRC Environmental Corporation

Table 1
Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (ASTM 5755 Dust)


33787-0010-0002; Tishman Construction; Battery Maritime Building

SciLab Sample #	Client Sample #	Surface Area Sampled (sq. cm)	Dilution Factor	Asbestos Structures Detected	* Analytical Sensitivity on Grid (Stu / sq mm)	Structure Density on Grid (Stu / sq mm)	* Analytical Sensitivity on Surface (Stu / sq. cm)	Structure Density on Surface (Stu / sq. cm)	Type of Asbestos
01	0503-PF-01	100.0	0.003	1	10	20.0	6,420	12,840	chrysotile
	2nd Fl. Ventr. Rm. On SE Corner								
02	0503-PF-02	25.0	0.002	3	10	30.0	30,240	102,720	chrysotile
	2nd Fl. Lobby B On SW Corner								
03	0503-PF-03	25.0	0.002	9	10	90.0	34,240	101,160	chrysotile
	2nd Fl. West Side Of Main Concourse								
04	0503-PF-04	25.0	0.003	1	10	10.0	25,680	25,680	chrysotile
	2nd Fl. East Side Of Main Concourse								
05	0503-PF-05	100.0	0.002	0	10	<10	8,560	<8,560	NSD
	2nd Fl. Office On East Side Of 2nd Fl.								
06	0503-PF-06	100.0	0.002	0	10	<10	8,560	<8,560	NSD
	2nd Fl. Office On North East Corner Of 2nd Fl.								
07**	0503-PF-07				1				
	Field Blank								

* structure density represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By: Analyzed By: 

Alexander Barenzola

Date: 5/4/02

CITY_21MC100_003025321

MAY 7 2002 4:29 PM
 05/05/2002 12:32
 2125799382

SCILAB INC.

NO. 3894 PAF 4/3/03
 PAGE 82/83