

01/30/02 WED 13:38 FAX 518 485 1150
01/22/02 TUE 09:23 FAX 518 485 1150

NYSDOL-PESH
NYSDOL-PESH

010
001

**New York State Department of Labor
Public Employee Safety and Health Bureau**

Vehicle Contamination Sampling

SAMPLE # 7

Vehicle Location or ID: Fleet Maint. Ctr. 34th St. Long Island City

Vehicle Type: FP02002 283

Asbestos

	Before vents turned on	After vents turned on
Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

	<u>Metals</u>	
Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>✓ Back seat Drivers Side</u>	<u>Back seat</u>
	<u>Other: 5" x 10 1/2"</u>	<u>Other:</u>

	Other:	
Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Sample Date: 1/22/02

Sampled By: Kevin Cox