

NL

**New York State Department of Labor
Public Employee Safety and Health Bureau**

Vehicle Contamination Sampling

SAMPLE # 1/14/02-#1-9

Vehicle Location
or ID:

E #217 - 48-58 35th St. FDNY Garage

Vehicle Type:

Seagrave Pumper Truck (Engine)

Asbestos

	Before vents turned on	After vents turned on
Sample Location of wipe:	☒ Dashboard #1	☒ Dashboard #2
	☐ Front seat	☐ Front seat
	☐ Floor	☐ Floor
	☐ Back seat	☐ Back seat
	☐ Other:	☒ Other: Console in rear cab - #3
		☒ Right Rear hose bay - #9

Metals

Sample Location of wipe:	☐ Dashboard	☐ Dashboard
	☐ Front seat	☐ Front seat
	☐ Floor	☐ Floor
	☐ Back seat	☒ Back seat - #6
	☐ Other:	☒ Other: Console in front cab - #4
		☒ Left Rear hose bay - #8
	Other: <u>Mercury</u>	
Sample Location of wipe:	☐ Dashboard	☐ Dashboard
	☐ Front seat	☐ Front seat
	☐ Floor	☐ Floor
	☐ Back seat	☒ Back seat - #7
	☐ Other:	☒ Other: Console in front cab - #5

— truck had been decontaminated by LVI, Inc. (HEPA vac., wet wipes)

Sample Date:

1/14/02

Sampled By:

M. Thorsland / C. Jay