NYC 9/11 Public Portal Document

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 1-17-02 # 22-28

Vehicle Location or ID: Engine 5 – 340 E. 14th St.

Vehicle Type: Engine 5 (Seagrave) Truck

Asbestos

Sample Location of wipe:	Before vents turned on	After vents turned on
	X Dashboard – 22	___ Dashboard
	___ Front seat	___ Front seat
	___ Floor	___ Floor
	___ Back seat	___ Back seat
	___ Other:	X Other: front of blower unit near floor (24)

X – (26) near blower unit rear cab

Metals

Sample Location of wipe:		
	X Dashboard – 23	___ Dashboard
	___ Front seat	X Front seat (25)
	___ Floor	___ Floor
	___ Back seat	___ Back seat
	___ Other:	X Other: middle console rear cab – 27

Other: Mercury

Sample Location of wipe:		
	___ Dashboard	___ Dashboard
	___ Front seat	___ Front seat
	___ Floor	X Floor – rear cab – 28
	___ Back seat	___ Back seat
	___ Other:	___ Other:

Truck was @ site – arrived before 2nd impact – there for 2 days (in-house decon)

Sample Date: 1/17/02

Sampled By: M. Thorsland, C. Jay

NYC-WTC_000208497