

**New York State Department of Labor
Public Employee Safety and Health Bureau**

Vehicle Contamination Sampling

SAMPLE # 1-17-02-#29-36

Vehicle Location
or ID:

Engine 39-ladder 16-157 E. 67th St.

Vehicle Type:

Ladder 16 (Seagrave) - # SL9414

Asbestos

Sample Location
of wipe:

Before vents turned on

After vents turned on

☒ Dashboard - 29
☐ Front seat
☐ Floor
☐ Back seat
☐ Other:

☐ Dashboard
☐ Front seat
☐ Floor
☐ Back seat

☒ Other: blower unit near
windshield - 31

(34)
☒ X - ceiling vent
(rear seat area)

Metals

Sample Location
of wipe:

☐ Dashboard
☐ Front seat
☐ Floor
☐ Back seat

☒ X Other: Middle console (30)

☐ Dashboard
☐ Front seat
☐ Floor
☐ Back seat

☒ X Other: Middle console (32)

X - ceiling vent (35)
(rear seat area)

Other: Mercury

Sample Location
of wipe:

☐ Dashboard
☐ Front seat
☐ Floor
☐ Back seat
☐ Other:

☒ X Dashboard
☒ X Front seat (driver) - 33
☒ X Floor - rear cab area (36)
☐ Back seat
☐ Other:

Truck was at site - arrived after 2nd impact
(in-house decon) there for one day

Sample Date:

1/17/02

Sampled By:

M. Thorsland / C. Jay