NYC 9/11 Public Portal Document

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 1/15/02 - #21 - 28

Vehicle Location or ID: Engine 7 Ladder 1 – 100 Duane St.

Vehicle Type: Engine 7 (Pumper truck)

Asbestos

Sample Location of wipe:	Before vents turned on	After vents turned on
	X Dashboard (#21)	X Dashboard – #24
	___ Front seat	___ Front seat
	___ Floor	___ Floor
	___ Back seat	___ Back seat
	___ Other:	X Other: rear console – #26

Metals

Sample Location of wipe:		
	X Dashboard (#22)	___ Dashboard
	___ Front seat	X Front seat (passenger) – #25
	___ Floor	___ Floor
	___ Back seat	___ Back seat
	___ Other:	X Other: rear cab wall – #27

Other: Mercury

Sample Location of wipe:		
	___ Dashboard	___ Dashboard
	X Front seat (passenger) #23	___ Front seat
	___ Floor	___ Floor
	___ Back seat	X Back seat – #28
	___ Other:	___ Other:

Replacement truck (original rigs were destroyed)

Sample Date: 1/15/02

Sampled By: M. Thorsland / C. Jay

NYC-WTC_000208551