

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 1-17-02-[#]22-28

Vehicle Location
or ID:

Engine 5 - 340 E. 14th St,

Vehicle Type:

Engine 5 (Seagrave) Truck

Asbestos

Sample Location
of wipe:

Before vents turned on

After vents turned on

☒ Dashboard-22
☐ Front seat
☐ Floor
☐ Back seat
☐ Other:

☐ Dashboard
☐ Front seat
☐ Floor
☐ Back seat
☒ Other: front of blower unit
near floor (24)

(26)
X - near blower
unit rear cab

Metals

Sample Location
of wipe:

☒ Dashboard-23
☐ Front seat
☐ Floor
☐ Back seat
☐ Other:

☐ Dashboard
☒ Front seat (25)
☐ Floor
☐ Back seat
☒ Other: middle console
rear cab-27

Other: Mercury

Sample Location
of wipe:

☐ Dashboard
☐ Front seat
☐ Floor
☐ Back seat
☐ Other:

☐ Dashboard
☐ Front seat
☒ Floor - rear cab-28
☐ Back seat
☐ Other:

Truck was @ site - arrived before 2nd impact - there for 2 days
(in-house decon)

Sample Date:

1/17/02

Sampled By:

M. Thorland, C. Jay