



Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1676

CHAIN OF CUSIL

FUR ABESDUS AIR MONITORING

CLIENT: NYC-DDC

SAMPLING DATE:

4-19-02

PROJECT: Stuyvesant H.S.

ADDRESS: 345 Chambers St., NY, NY 10282

Fax: (718) 729-1676

Толы 19А

[illegible]

TECHNICIAN: Renata Dymkowska

ROTAMETER KAM101

CHAIN OF CUSTODY	FAX results to DDC	RECEIVED AT LAB BY: <i>JS</i> SAMPLE CONDITION UPON RECEIPT: <i>Good</i> DATE/TIME:
------------------------	--------------------	---

ANALYST. ALEX BARONCO

DATE RECEIVED: 4-20-92

DATE OF ANALYSIS 4-20-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method

FAX RESULTS TO (212) 944-5356