

PAGE 01/01



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.
Pier 25

SAMPLING DATE: 04-07-02
ADDRESS: 345 Chambers St, NY, NY 10282

7020407A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ³)	Structure Concentration (struc/cc)
							0.5-5.0 (µ)	>5.0 (µ)		
01	North School Entrance-West Side	07:43	07:27	3	3	1752	0	0	420.0	40.0044
02	" - East Side	07:47	07:29	3	3	1749	0	0	422.2	40.0044

TECHNICIAN: L. PROCHNIEWICZ

ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE FAX RESULTS	RECEIVED AT LAB BY: <i>[Signature]</i>
	TO DDC -EHSS	SAMPLE CONDITION UPON RECEIPT: <i>Good</i>
		DATE/TIME:

ANALYST: *ALEXS BARNES* DATE RECEIVED: *4-8-02* DATE OF ANALYSIS: *4-8-02*

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356

KAM CONSULTANTS
REC'D
APR - 7 PM 4:29

KAM CONSULTANTS

7187293774

04/08/2002 10:37

CITY_21INC100_010394975