

PAGE 01/02

KAM CONSULTANTS

7187293774

09:17

04/07/2002

CITY_21NC100_010394976



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, NY 11106
Tel: (718) 729-1997
Fax: (718) 729-1878

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

Pir#25

SAMPLING DATE: 04-06-02
ADDRESS: 345 Chambers St., NY, NY 10282

7320406 C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (structures/m ²)	Structure Concentration (structures)
							0.5-5.0 (µ)	>5.0 (µ)		
01	North School Entrance - West Side	08:04	17:46	3	3	1746	0	0	< 20.0	602049
02	" - East Side	08:07	17:48	3	3	1743	0	0	< 20.0	602049

TECHNICIAN: L. PROCHNIEWICZ

ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE FAX RESULTS TO DDC -EHSS	RECEIVED AT LAB BY: <i>[Signature]</i>
		SAMPLE CONDITION UPON RECEIPT: <i>[Signature]</i>
		DATE/TIME:

ANALYST: ALEXANDER GINS DATE RECEIVED: 4-6-02 DATE OF ANALYSIS 4-7-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5358