



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 3/21/02
ADDRESS: 345 Chambers St., NY, NY 10282
KAM CONSULTANTS

2002 MAR 21 PM 4:51

T020321C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struct/mm ³)	Structure Concentration (struct/cc)
							0.5-5.0 (µ)	>5.0 (µ)		
1	Piez # 25 NORTH EXIT OF STUYVESANT H.S.	1700	1700	3	3	1800	0	0	4200	400043
2	North west site	1701	1701	3	3	1800	0	0	4200	400043

TECHNICIAN: D. SALLS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX RESULTS TO NYC D.D.C	RECEIVED AT LAB BY: G-2
		SAMPLE CONDITION UPON RECEIPT: Good
		DATE/TIME:

ANALYST: ALEXS BARELOV? DATE RECEIVED: 3-21

DATE OF ANALYSIS 3-22-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (ASHERA)

Sample Volume may be below recommended limit of the method.

FAX RESULTS TO (212) 911-5356

CITY_21NC100_010394984