

PAGE 01/01

KAM CONSULTANTS

7187293774

02/15/2002 16:45

CITY_21MC100_010395036



33-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 2-15-02
ADDRESS: 345 Chambers St., NY, NY 10282

T020215U

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (fibr/mm ³)	Structure Concentration (fibr/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
1	PIER 25 North Entrance of school - East	7:00	17:00	3	3	1800	0	0	2200	2000043
2	North Entrance of school - West	7:01	17:01	3	3	1800	0	0	2200	2000043

TECHNICIAN: Renata Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results to DDC.	RECEIVED AT LAB BY: <i>ms</i>
		SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST: ALEXS BARENBOUR DATE RECEIVED: 2-15-02 DATE OF ANALYSIS: 2-15-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RESULTS TO (212) 941-5356