



35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 1/28/02
ADDRESS: 345 Chambers St., NY, NY 10282

T 020129 A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
1	Piez #25 NORTH EXIT OF STUYVESANT H.S.	07:00	17:00	3	3	1800	0	0	< 20.00	< 20.00
2	North west site	07:01	17:01	3	3	1800	0	0	< 20.00	< 20.00

TECHNICIAN

D. SALIS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX RESULTS TO	RECEIVED AT LAB BY:
	N.Y.C D.D.C	SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST

[Signature]

DATE RECEIVED:

1/29/02

DATE OF ANALYSIS

1/29/02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method.

RESULTS TO (212) 941-5356

CITY_21MC100_010395121