NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718)729-1997
Fax: (718)729-1876

CHAIN OF CUSTOL FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12-12-01
ADDRESS: 345 Chambers St., NY,NY 10282

TO 11212 B

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER 25									
1	North Entrance of school - East	00.02	8:01	3	3	1437	0	0	<.1852	<0.0050
2	-11 —— 11 —— West	00.03	8:02	3	3	1437	0	0	<.1852	<0.0050

RECEIVED
KAM CONSULTANTS
2001 DEC 12 AM 8:47

TECHNICIAN: Renata Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	RECEIVED AT LAB BY:
FAX results to DDC.	SAMPLE CONDITION UPON RECEIPT:
	DATE/TIME:

ANALYST:

DATE RECEVED: 12/12

DATE OF ANALYSIS 12/12

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RSULTS TO (212) 941-5356

12/12/2001 13:01 7187293774 KAM CONSULTANTS PAGE 03/03
CITY_21MC100_010395189
NYC-WTC_000208829