NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTOL FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12/12/01
ADDRESS: 345 Chambers St., NY, NY 10282

T0112BB

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER #25									
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	16:01	23:58	3	3	1431	0	0	<18.52	<0.005
2	↓ - WEST SIDE	16:02	23:59	3	3	1431	0	0	<18.52	<0.005

TECHNICIAN: A. MARTIROSSIAN

ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE, FAX RESULTS TO NYC DOC	RECEIVED AT LAB BY: ML SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

RECEIVED KAM CONSULTANTS 2001 DEC 13 AM 7:55

ANALYST: [signature] DATE RECEVED: 12/13 DATE OF ANALYSIS 12/13

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

PAGE 02
KAM CONSULTANTS
7187293774
12/13/2001 13:02
CITY_21MC100_01039191

NYC-WTC_000208830