



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, NY 11106
Tel: (718) 729-1876
Fax: (718) 729-1876
2001 DEC 15

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12/14/01
ADDRESS: 345 Chambers St., NY, NY 10282

AM 8:10

10/12/01

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
1	PIER #25 OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	16-01	23.57	3	3	1928	0	0	<16.67	20.0045
2	↓ - WEST SIDE	16-01	23.58	3	3	1928	0	0	<16.67	20.0045

TECHNICIAN: A. MARTINESSIAN

ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE, FAX RESULTS TO NYC DDC	RECEIVED AT LAB BY: <i>[Signature]</i>
		SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST: *[Signature]* DATE RECEIVED: 12/15 DATE OF ANALYSIS 12/15

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356

CITY_21MC100_010395197