

**KAM CONSULTANTS**  
35-40 36th Street  
Long Island City  
New York, 11106  
Tel: (718) 729-1997  
Fax: (718) 729-1876



## CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

**CLIENT: NYC-DDC**  
**PROJECT: Stuyvesant H.S.**

SAMPLING DATE: 11/2/01  
ADDRESS: 345 Chambers St., NY, NY 10282

Т 01102 К

[illegible]

TECHNICIAN: A. MAROTROSSIAN / R. DYMKOWSKA ROTAMETER: KAM101

|                        |                                   |                                                                                        |
|------------------------|-----------------------------------|----------------------------------------------------------------------------------------|
| CHAIN<br>OF<br>CUSTODY | PLEASE, FAX RESULTS TO<br>NYC DDC | RECEIVED AT LAB BY: <i>[Signature]</i><br>SAMPLE CONDITION UPON RECEIPT:<br>DATE/TIME: |
|------------------------|-----------------------------------|----------------------------------------------------------------------------------------|

ANALYST: ALERS DORE ROY DATE RECEIVED: 11/2/01 DATE OF ANALYSIS 11/03/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)  
Sample Volume may be below recommended limit of the method.  
FAX RESULTS TO (212) 941-5356