



35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 11/30/01
ADDRESS: 345 CHAMBERS ST., NY NY 10282
RAN CONSULTANTS

2001 NOV 30 PM 5:34

7011201A

[illegible]

TECHNICIAN: D. SALLS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX RESULTS TO N.Y.C D.D.C.	RECEIVED AT LAB BY: MS SAMPLE CONDITION UPON RECEIPT: DATE/TIME:
------------------------	--------------------------------	--

ANALYST: ALEXS BARENBOID DATE RECEIVED: 12-30

DATE OF ANALYSIS 12-01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356