NYC 9/11 Public Portal Document

35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1976

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.
SAMPLING DATE: 11-22-01
ADDRESS: 345 Chambers St., NY, NY 10282

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	Prev-25								Tot/Cl/Cl/B	
1	North Entrance of school - East	16:01	23:58	3	3	1431	0	0	4/6.67	<0.0045
2	-u — " — West	16:03	23:59	3	3	1428	d	d	↓	↓

TECHNICIAN: R. Dymkowska / A. MARTIROSIAN ROTAMETER: KAM101

CHAIN OF CUSTODY		RECEIVED AT LAB BY:
	FAX Results to DDC.	SAMPLE CONDITION UPON RECEIPT: Good
		DATE/TIME:

ANALYST: ALEKS BARENBOIM DATE RECEIVED: 11-23 DATE OF ANALYSIS 11-25

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

RECEIVED
KAM CONSULTANTS
2001 NOV 23 PM 2:12

KAM CONSULTANTS 7187293774 11/23/2001 12:04 PAGE 02/05

CITY_21MC100_0103953351

NYC-WTC_000208841