



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 11/28/01
ADDRESS: 345 Chambers St., NY, NY 10282

T011128B1

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (ppm)	FLOW AFTER (ppm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (structures/m ³)	Structure Concentration (structures/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
1	Piez # 25 NORTH EXIT OF STUYVESANT H.S.	0800	1600	3	3	1440	0	0	<16.67	<0.0045
2	North west side	0801	1601	3	3	1440	0	0	<16.67	<0.0045

TECHNICIAN: D. SALIS
ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX: Results to N.Y.C. D.D.C.	RECEIVED AT LAB BY: <i>[Signature]</i>
		SAMPLE CONDITION UPON RECEIPT: Good
		DATE/TIME: 11/28/01

ANALYST: *[Signature]* DATE RECEIVED: 11/28 DATE OF ANALYSIS 11/29

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356

RECEIVED
KAM CONSULTANTS
2001 NOV 28 PM 5:44

CITY_21INC100_010395358