NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
NewYork, 11106
Tel: (718) 729-1997
Fax: (718) 729-1676

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-09-01
ADDRESS: 345 Chambers St., NY,NY 10282

T0110/0A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	Pier#25 - Across of North Exit of Stuyvesant H.S.	20:52	23:55	7	7	1281	2	1	42.86	0.0128
2	Pier#25 - East Side - By Truck Unloading Area	20:57	23:59	7	7	1274	0	0	<14.29	<0.0043

TECHNICIAN: A. DIMITROPOULOS

ROTAMETER: KAM101

CHAIN OF CUSTODY	Please analyse ASAP & fax results to DDC-Hazmat (718) 391-1499 DDC-Operations (212) 941-5356 DDC-Bob Adams (609) 584-1134	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME: 10/10/01

ANALYST: DATE RECEVED: DATE OF ANALYSIS

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

PAGE 01/01
KAM CONSULTANTS 7187293774
10/10/2001 07:58
CITY_21MC100_010395377

NYC-WTC_000208847