KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10/10/01
ADDRESS: 345 Chambers St., NY,NY 10282

T011011A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	PIEZ#25 ACZOS NORTH WEST EX OR STUYVESANT H.S	1600	2400	3	3	1440	0	0	<16.67	<0.0045
2	PIEZ#25 NORTH WEST OR STUYVESANT H.S.	1601	2401	3	3	1440	1	0	16.67	0.0045

TECHNICIAN: Dimitrios M. Salis

ROTAMETER: KAM101

CHAIN OF CUSTODY		RECEIVED AT LAB BY:
		SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST: Dave Chen DATE RECEVED: 10/11/01 DATE OF ANALYSIS 10/11/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

RECEIVED KAM CONSULTANTS 2001 OCT 11 AM 4:41

KAM CONSULTANTS 7187293774 10/11/2001 07:51