NYC 9/11 Public Portal Document

35-40 38th Street
Long Island City
New York, 11106
Tel: (718) 729-1937
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-22-01
ADDRESS: 345 Chambers St., NY, NY 10282

RECEIVED
KAM CONSULTANTS
2001 OCT 22 PM 5:11

TOC 022E

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	North Entrance of H.S-East	0759	1659	3	3	1440	0	0	< 16.67	< 0.005
2	North Entrance of H.S-West	0801	1601	3	3	1440	↓	↓	↓	↓

TECHNICIAN: R. Dymkowska
ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results to DDC.	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: ALEKS DABROWSKI DATE RECEVED: 10/22/01 DATE OF ANALYSIS 10/22/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

PAGE 01/02
KAM CONSULTANTS 7187293774
10/22/2001 16:21
CITY_21MC100_010395425

NYC-WTC_000208857