NYC 9/11 Public Portal Document

35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-25-01
ADDRESS: 345 Chambers St., NY, NY 10282

T011025O1

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER-2.5									
1	North Entrance of H.S-East	8:01	15:58	3	3	1431	0	0	<16.67	<0.0045
2	North Entrance of H.S-West	8:03	16:00	3	3	1431	0	0	<16.67	<0.0045

RECEIVED
KAM CONSULTANTS
2001 OCT 25 PM 7:30

TECHNICIAN: R. Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results to DDC.	RECEIVED AT LAB BY: [signature]
		SAMPLE CONDITION UPON RECEIPT: Good
		DATE/TIME: 10-25-01

ANALYST: [signature] DATE RECEIVED: 10/26 DATE OF ANALYSIS 10/26

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

PAGE 02/04 KAM CONSULTANTS 7187293774 10:04 10/26/2001 CITY_21MC100_010395434

NYC-WTC_000208859