



35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-28-01
ADDRESS: 345 Chambers St., NY, NY 10282

T01C029A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
	PIER-25									
1	North Entrance of H.S. East	8:01	16:01	3	3	1440	0	0	46.67	20.0045
2	11 West	8:03	16:03	3	3	1440	↓	↓	↓	↓

RECEIVED
KAM CONSULTANTS
2001 OCT 28 PM 5:27

TECHNICIAN: R. Dymkawska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Result to DDC.	RECEIVED AT LAB BY: MS
		SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST: ALEXS BARRERAS DATE RECEIVED: 10/29/01 DATE OF ANALYSIS 10/29-01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356

CITY_21MCI00_010395443

10/29/2001 11:48 7187293774 KAM CONSULTANTS PAGE 01/03