



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1897
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-14-01
ADDRESS: 345 Chambers St., NY, NY 10282

7011014M

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struct/mm ²)	Structure Concentration (struct/cc)
							0.5-5.0 (µ)	>5.0 (µ)		
	DIER-25									
1	North Entrance of school - East	7:57	15:54	3	3	1451	0	0	<16.67	<0.0045
2	North Entrance of school - West	8:00	15:57	3	3	1431	0	0	<16.67	<0.0045

TECHNICIAN:

ROTAMETER: KAM101

CHAIN OF CUSTODY	Pleas analyze HSP and FAX Receipt	RECEIVED AT LAB BY: <i>[Signature]</i>
	DDC Hazmat (718) 391-1439	SAMPLE CONDITION UPON RECEIPT:
	DDC Operational (212) 941-5356	DATE/TIME: 10/14/01
	DDC FIOR ADAMS (609) 584-1134	13-V-111-11-130-1002

ANALYST: *[Signature]*

DATE RECEIVED: 10/14/01

DATE OF ANALYSIS: 10/14/01
RECEIVED KAM CONSULTANTS

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356

CITY_21NC100_010395459