



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: **RECEIVED**
KAM CONSULTANTS
ADDRESS: 345 Chambers St., NY, NY 10282

2001 OCT 11 AM 9:41

T011011C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struct/min ³)	Structure Concentration (struct/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
	<u>PIER # 25</u>									
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	00.11	8.16	3	3	1485	0	0	<16.67	<0.0045
2	OUTSIDE NORTH ENTRANCE OF SCHOOL - WEST SIDE	00.12	8.17	3	3	1485	0	0	<16.67	<0.0045

TECHNICIAN: A. MARTIROSSIAN

ROTAMETER: KAM101

CHAIN OF CUSTODY	PIERS, MANHATTAN ASBESTOS AIR MONITORING RESULTS:	RECEIVED AT LAB BY: <u>[Signature]</u>
	DDC LABORATORY (718) 391-1499	SAMPLE CONDITION UPON RECEIPT:
	DDC OPERATIONS (212) 941-5356	DATE/TIME: <u>10/11/01</u>
	BOB ROBINSON (619) 584-1139	

ANALYST: [Signature]

DATE RECEIVED: 10/11/01

DATE OF ANALYSIS 10/11/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (ASHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356