NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

ANALYSIS REPORT
ASBESTOS IN AIR
Transmission Electron Microscopy

CLIENT: Department of Design and Construction - 30-30 Thomson Avenue, Long Island City, NY 11101
PROJECT ADDRESS: *Stuyvesant H.S., 345 Chambers St., NY, NY 10282 Pier #25 - Outside School North Side by Water*

Lab ID#	Client Sample ID#	Sample Location	Volume (liters)	Grid Openings Examined	Filter Area (mm^2)	Analytical Sensitivity (struct/cc air)	Asbestos Type(s)	Asbestos Structures (microns) 0.5-5.0	>5.0	Detected Total	Structure Density ($struc/mm^2$) Total	Structure Concentration (struc/cc) Total
T020409A-01	1	East Pump	1779	5	385	0.0043	ND	0	0	0	<20.00	<0.0043
T020409A-02	2	West Pump	1776	5	385	0.0043	ND	0	0	0	<20.00	<0.0043

Area Analyzed: 0.0500 mm^2
Grid Opening Area: 0.010 mm^2
Date Collected: 04/08/02(7:30-17:00)

Date Received: 04/09/02
Date Analyzed: 04/09/02
Date of Report: 04/09/02

Analyst: AB
Alex Barengolts

Lab Manager: DC
David Chen

Analysis performed according to AHERA Method (EPA 40 CFR Part 763 - Appendix A).Samples will be stored for ninety (90) days and then returned to the client upon request.
Sample volume is below recommended limit of the method

AIHA #: 100269 **NIST-NVLAP # : 102047** **NYS-DOH ELAP#: 11273**

CITY_21MC100_010404603

NYC-WTC_000208973