NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTOL FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 3/26/02
ADDRESS: 345 Chambers St., NY, NY 10282

T0203.27A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	North Pier #25 EXIT OF STUYVESANT H.S	0700	1700	3	3	1800	0	0	<20.0	<0.0043
2	North west site	0701	1701	3	3	1800	0	0	<20.0	<0.0043

TECHNICIAN: D. SALLS
ROTAMETER: KAM101

CHAIN OF CUSTODY	FOX RESULTS TO N.Y.C. DDC	RECEIVED AT LAB BY:	
		SAMPLE CONDITION UPON RECEIPT:	Good
		DATE/TIME:	

ANALYST: ALEKS BARENBOLD DATE RECEVED: 3-27-02 DATE OF ANALYSIS 3-27-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

RECEIVED KAM CONSULTANTS 2002 MAR 27 21

CITY_21MC100_009251398

NYC-WTC_000208978