NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

# CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 03-31-02
ADDRESS: 345 Chambers St., NY,NY 10282

T0204021A

| FIELD DATA | | | | | | | LAB ANALYSIS | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| SAMPLE # | LOCATION | TIME IN | TIME OUT | FLOW BEF. (lpm) | FLOW AFTER (lpm) | VOLUME (liters) | STRUCTURES DETECTED 0.5-5.0 (μ) | STRUCTURES DETECTED >5.0 (μ) | Structure Density (struc/mm²) | Structure Concentration (struc/cc) |
| 01 | North School Entrance-West Side | 08:05 | 17:46 | 3 | 3 | 1743 | 0 | 0 | < 20.0 | < 0.0044 |
| 02 | " - East Side | 08:08 | 17:48 | 3 | 3 | 1740 | 0 | 0 | < 20.0 | < 0.0044 |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

RECEIVED
KAM CONSULTANTS
2002 APR -2 A 7:53

TECHNICIAN: L. PROCHNIEWICZ
ROTAMETER: KAM101

| CHAIN OF CUSTODY | PLEASE FAX RESULTS TO DDC-EHSS | RECEIVED AT LAB BY: MB<br>SAMPLE CONDITION UPON RECEIPT: Good<br>DATE/TIME: |
|---|---|---|

ANALYST: ALEKSANDR MOLOD DATE RECEVED: 4-2-02 DATE OF ANALYSIS 4-2-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009251403

NYC-WTC_000208980